


**SPARE PARTS CATALOGUE**  
**: CEORA™ LADESTATION CS4**

Spare Parts List

---

# **SPARE PARTS LIST**


**A** CEORA CS4  
CHARGING STATION



PXM_REF	PXM_PARTNO	BESCHREIBUNG	PXM_REMARK	
1	598473301	HUT	Cap	1
2	529469201	MAGNET	Magnet	1
3	598473401	RAHMEN	Frame	1
4	575543314	SCHRAUBE	Screw	8
5	734113741	SCHEIBE	Washer	4
6	598474401	SCHALTBRETT	Panel	2
7	598474201	SCHALTBRETT	Panel	1
8	599345601	KNOPF	Button	1
9	580504101	ANSCHLUSSELEMENT	Terminal	10
10	525755105	SCHRAUBE	Screw	20
11	598474202	SCHALTBRETT	Panel	1
12	574487001	FEDER	Spring button	1
13	598474101	GEHÄUSE	Housing Tower	1
14	597665601	ANTRIEBSEINHEIT	Power supply unit 12A EU/ UK/IR/CH/AU/NZ. FROM S/N 221502008	1
14	597665604	ANTRIEBSEINHEIT	Power supply unit 12A US.CDA. FROM S/N 221502008	1
14	537679801	VERKABELUNG KPL.	Power supply unit EU + Mains cable EU. UP TO S/N 221502007	1
14	537679802	VERKABELUNG KPL.	Power supply unit EU + Mains cable UK. UP TO S/N 221502007	1
14	537679803	VERKABELUNG KPL.	Power supply unit EU + Mains cable CH. UP TO S/N 221502007	1
14	537679804	VERKABELUNG KPL.	Power supply unit US + Mains cable US. UP TO S/N 221502007	1
15	598973301	VERKABELUNG KPL.	Mains cable EU. FROM S/N 221502008	1
15	598973305	VERKABELUNG KPL.	Mains cable AU/NZ	1
15	598973302	VERKABELUNG KPL.	Mains cable UK/IR. FROM S/N 221502008	1
15	598973304	VERKABELUNG KPL.	Mains cable US/CA. FROM S/N 221502008	1
15	598973303	VERKABELUNG KPL.	Mains cable CH. FROM S/N 221502008	1
15	536621201	VERKABELUNG KPL.	Mains cable EU. UP TO S/N 221502007	1
15	536621202	VERKABELUNG KPL.	Mains cable UK. UP TO S/N 221502007	1
15	536621203	VERKABELUNG KPL.	Mains cable CH. UP TO S/N 221502007	1
15	536621204	VERKABELUNG KPL.	Mains cable US. UP TO S/N 221502007	1
16	598973401	VERKABELUNG KPL.	Mains cable PSU Secondary side	1
17	504124101	FEDER	Spring hatch	2
18	599144501	STÄNDER	Stand	1
19	599645302	DICHTSCHEIBE	Grommet	1
20	574874719	DICHTUNGSTREIFEN	Sealing strip	1
21	597427501	PLATINE KPL.	Charging station circuit board	1
22	598964101	VERKABELUNG KPL.	Wiring assy Generator board 6P	1
23	598960101	VERKABELUNG KPL.	Wiring assy Generator board 8P	1
24	579460502	ABSTANDSSCHEIBE	Spacer	4
25	580511401	FEDER	Spring	4
26	598953401	VERKABELUNG KPL.	Wiring assy	1
27	574450101	SCHRAUBE	Screw	4
28	599345201	GEHÄUSE	Housing Front	1
29	598474001	DECKEL	Lid Front	1
30	590217201	LINSE	Lens	2
31	598472901	PLATTE	Charging station baseplate upper	2
32	599436301	GETRIEBE	Coupling	8
33	599547801	STÜTZE	Support plate	2
34	598960001	VERKABELUNG KPL.	Wiring assy	1
35	598472801	BASE	Charging station baseplate lower	1

**B** CEORA CS4  
ACCESSORIES

1



---

PXM_REF	PXM_PARTNO	BESCHREIBUNG	PXM_REMARK		
1	535423101	STÜTZPLATTE	Support plate KIT. AT, BE, DK, FR, DE, NL, PL, SE, CH, UK	1	
1	535423110	STÜTZPLATTE	Support plate KIT. US	1	
2	597435801	SCHRAUBE	Anchor Screw kit	6	
3	574450101	SCHRAUBE	Screw	13	